

(GW/UST-2)

Site Investigation Report For Permanent Closure or Change-in-Service of U.S.T.

FOR
TANKS
IN
NC

Return Completed Form To:

The appropriate DEM Regional Office according to the county of the facility's location.
[SEE MAP ON REVERSE SIDE OF OWNER'S COPY (PINK) FOR REGIONAL
OFFICE ADDRESS].

RECEIVED
State Use Only
N.C. Dept. of ENR
I.D. Number
Date Received JUN 07 1993

INSTRUCTIONS

Complete and return within (30) days following completion of site investigation.

I. Ownership of Tank(s)

II. Location of Tank(s)

Abandoned Tanks on NCDOT Right-of-Way

Owner Name (Corporation, Individual, Public Agency, or Other Entity)

NCDOT

Street Address

PO Box 25201

County

Wake

City Raleigh

State NC

Zip Code

27611

Area Code

919

Telephone Number

250-4088

NCDOT ROW

Facility Name or Company

Adjacent to Quality Printing

Facility ID # (if available)

NA

Street Address or State Road

6700 West Market St.

County

Guilford

City

Greensboro

Zip Code

27407

Area Code

Telephone Number

919-852-4072

III. Contact Person

Gregory Smith

Name

Environmental Geologist

Job Title

(919) 250-4088

Telephone No. (Area Code)

Closure Contractor

Aquaterra, Inc/Four Seasons

(Name)

319J South Westgate Dr. GSO, NC

(Address)

919-852-5003

Telephone No. (Area Code)

Lab Hydrologic, Inc.

1003 Twilight Trail

(Name)

Frankfort KY 40601

(Address)

(502) 223-0251

Telephone No. (Area Code)

IV. U.S.T. Information

V. Excavation Condition

VI. Additional Information Required

Tank No.	Size in Gallons	Tank Dimensions (D) x (L)	Last Contents	Water in Excavation		Free Product		Notable Odor or Visible Soil Contamination	
				Yes	No	Yes	No	Yes	No
1	1,000	46" X 12'	petroleum		✓		✓		✓
1	750	5' X 6'	petroleum		✓		✓		✓

See reverse side of pink copy (owner's copy) for additional information required by N.C. - DEM in the written report and sketch.

VII. Check List

Check the activities completed.

- ☒ Contact local fire marshal
☒ Notify DEM Regional Office before abandonment.
☒ Drain & flush piping into tank.
☒ Remove all product and residuals from tank
☒ Excavate down to tank
☐ Clean and inspect tank.
☐ Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submersible pumps and other tank fixtures.
☐ Cap or plug all lines except the vent and fill lines.
☒ Purge tank of all product & flammable vapors.
☒ Cut one or more large holes in the tanks.
☒ Backfill the area.

Date Tank(s) Permanently closed: 1-27-93
Date of Change-in-Service:

ABANDONMENT IN PLACE

- ☐ Fill tank until material overflows tank opening;
☐ Plug or cap all openings;
☐ Disconnect and cap or remove vent line
☐ Solid inert material used - specify:

REMOVAL

- ☒ Create vent hole
☒ Label tank
☒ Dispose of tank in approved manner.
 Final tank destination: DH Griffin Wrecking Co.
 GSO NC

VIII. Certification (Read and Sign)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Print name and official title of owner or owner's authorized representative

Susan Kite Project Manager

Signature

Susan Kite

Date Signed

4-26-93